



Ardlussa Proposed Peatland Restoration - Site Location



Scale: 1: 418661



Scale 2 : 120837

- | | | |
|---|---|---|
|  Estate boundary |  restoration_lines Hag reprofiling |  restoration_points Dam |
|  Sub-sites outline |  Drain reprofiling |  Trench bund |
|  area_based_restoration Micro erosion repair |  Peat bank reprofiling |  Surface bund |
|  Scrub removal |  Wave dam |  Silt trap |
|  Gully block and reprofiling |  Wave dam and reprofiling |  OpenStreetMap |
|  bare_peat_stabilisation Geotextile |  Drain block and reprofiling | |
|  Turving |  Gully block and reprofiling | |



Contains Ordnance Survey data © Crown copyright and database rights 2026 OS 100017908
Aerial imagery from © Getmapping plc 2026

Base map and data from OpenStreetMap and OpenStreetMap Foundation (CC-BY-SA). © <https://www.openstreetmap.org> and contributors.

Created on: 25 Aug 2026 by Lucy Smtih, ACT Peatland ACTION Officer